5

10

Method For Acc ssing Electrical C mponents With Gloved Hands

ABSTRACT OF THE DISCLOSURE

A method for accessing electrical equipment with ASTM Class 00 and Class 0, gloves by a procedure wherein the gloves are periodically removed and put back on to accommodate sweat and heat development. Removal of the tight fitting gloves as well as putting them on is facilitated by the incorporation of a flock lining at those internal surfaces of the gloves which are exposed to important sweat generation. In order to enhance tool manipulation and maneuvering small components such as washers, bolts, nuts and the like, the glove exterior regions of finger tips, fingers and palm (the regions described as the work area of the glove) are made to have a rough surface.